SEA402623

			Hours														
Item Number	Date	Description	Operator	Labor	Backhoe	Jumping Jack Compacto	Cut-off Saw	Pick-up Truck F150	Laser*	Excavator w/ thumb*	Loader	Dozer	53" Vibratory Roller	Pipe Laser	Hoe Pac	Excavator w/ thumb	Dump Truck 14 Cy *
	11	Days Delay ManHours	114	40	6	0	0	0	30	35	46	0	0	0	5	0	35
20		Jeff asked Radian to stop digging footings and grade beams due to unsuitable soil to support building loads. Dug test pits Hangar B	2		2					1.	×	بركم	سرد				
33	8/26/99	Jeff asked Radian to use a backhoe to pot hole hangars A & C to determine the depth to native soil for PSI	1		1				,		364	7			**		
34-36	8/30/99	Over Excavation of Hangar C Footings and Grade Beams	8	4		i i			-/	4	4	-	$\Box$	一			
37-41	8/31/99	Back fill of Over Excavation of Hangar C Footings and Grade Beams with CDF / Over Excavation of Hangar B Footings and Grade Beams	6	7					2	) 3	3			)			
42-48	9/1/99	Back fill of Over Excavation of Hangar C Footings and Grade Beams with CDF / Back fill of Over Excavation of Hangar B Footings and Grade Beams with CDF	9	2	فتتس	\$ \frac{1}{2} \fra	, (1 %	je 4	2	1	8						6
49-56	9/2/99	Over Excavation & Backfill of Hangar B Footings and Grade Beams with CDF / Over Excavation & Backfill of Hangar A Footings and Grade Beams with CDF	23	5		198	المرام	42	5	5	9				.)		9
57-58	9/3/99	Backfill of Hangar B Footings and Grade Beams with CDF / Backfill of Hangar A Footings and Grade Beams with CDF		4	4	27	~ <del>*</del>		( <del>4</del>	17	3,000,000	<b>&gt;</b>	54	5		1	2.5
59-66 69-71	9/7/99	Backfill of Hangar B Footings and Grade Beams with CDF / Backfill of Hangar A Footings and Grade Beams with CDF	20	6	-7	5.4	,		6		) (8	Santa Chinara			5		3
72-76	9/8/99	Over Excavation & Backfill of Hangar A Footings and Grade Beams with CDF / Backfill of Hangar B Footings and Grade Beams with 4" Structural Fill & Compact	15	3	3	76	01		3	5	5						5
77-79		Beams with CDF / Cleaning Road Broom	12 (	3)		10	T.		-(3	5/4	4						4
80-84	9/10/99	Over Excavation & Backfill of Hangar A Footings and Grade Beams with CDF / Cleaning Road Broom	18	6				42	5	5	5		4				8

<sup>\*</sup> Rental of this equipment was for the removal of over excavated soils of the footings and grade beams. A minimum of two weeks rental is required regardless of hours.